टेलेक्स : 0397-208 वे॰ फ॰ पा॰

ग्राम । ने० फ० लि०

फोन : 2845, 3471 **से** 75

सो•एस॰टो॰/के ए ग्रार/7576 दि॰ 11-5-76 हरियाणा सै॰टै॰नं॰ के ए ग्रार/IV/16530 3-7-79

नेशनल फर्टिलाइज़र्स लिमिटेड

[भारत सरकार का उपक्रम] पानोपत-132106

संस्या/Ref. No. NFL/PT/TS/GE/



Telex : 0397-208 NFPT Gram : FERTNAT

Phone: 2845, 3471 to 75

C.S.T. KAR/CST/7576 dt. 11-5-76

Haryana Sales Tax No. KAR/IV/16530 dt. 3-7-79

national fertilizers limited

[A GOVT. OF INDIA UNDERTAKING] - PANIPAT-132106

दिनांक/Dated 8.4.91

TO WHOM IT MAY CONCERN

Our Incinerator Boiler SEA-101 of Sulphur Recovery Plant was retubed with tubes ASTM A-192 Size 31.80 mm OD x 2.9/5.9 thick and 2.20 mtrs long against Order No.SC/1403/86/8250 dated 29.8.86 at site by M/S Air Firge Industries in April/May, 1987. Performance of the Boiler had been quite satisfactory after retubing. Further we have not faced any problem on this equipment till this date. Certificate is being issued on the request of M/S Air Frige Industries vide their letter No.AS/AF/O1/589 dated 5.4.91.

(S.N.S DNEJA) 8)
Addl. Manager (G.E.)

DATE OF ACTUAL START OF WORK

6.3.87

ACTUAL DATE OF COMPLETION

14.5.87

PENALITY/LIQUIDATED DAMAGES IMPOSED : NIL

INSPECTED BY

: NFL/C.I.B. HARYANA

TUBE REPLACED

 $31.75 \text{ OD} \times 2.97 \text{ thk} \\ 31.75 \text{ OD} \times 5.97 \text{ thk}$

843 158

Total

: 1001

